

## ਦਫਤਰ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

Email ID: eecdsmuktsarpwdpb@gmail.com

ਵੱਲ,

ਪ੍ਰਿੰਸੀਪਲ,  
ਸੁਰਿੰਦਰ ਕੁਮਾਰ ਗੁਪਤਾ ਸਰਵਹਿੱਤਕਾਰੀ ਵਿੱਦਿਆ ਮੰਦਰ,  
ਸੀਨੀਅਰ ਸੈਕੰਡਰੀ ਸਕੂਲ, ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

ਨੰਬਰ: 3742

ਮਿਤੀ: 4-9-23

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਬਾਰੇ। ਸਾਲ 2023-24 (Sh. Surinder Kumar Gupta Sarvhitkari Vidya  
Mandir Senior Secondary School, Sri Muktsar Sahib.)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਬਿਨੈ-ਪੱਤਰ 2033 ਮਿਤੀ 24-06-2023

ਆਪ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ ਵੱਲੋਂ ਕਰ ਲਿਆ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾਂ ਦੀ ਰਿਪੋਰਟ ਦੇ ਆਧਾਰ ਤੇ ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋਂ ਠੀਕ ਹੈ ਅਤੇ ਵਰਤਣਯੋਗ ਹੈ। ਇਸ ਲਈ ਆਪ ਨੂੰ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਦੇ ਆਧਾਰ ਤੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇ ਸਿਵਲ ਵਰਕ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2023-24 (31 ਮਾਰਚ 2024) ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ :-

1. ਇਸ ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਸਾਲ ਮੁਰੰਮਤ ਕਰਵਾਈ ਜਾਵੇ।
2. ਇਸ ਬਿਲਡਿੰਗ ਦੀਆਂ ਛੱਤਾਂ ਉੱਪਰ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
3. ਜੇਕਰ ਬਿਲਡਿੰਗ ਵਿੱਚ ਕਿਸੇ ਤਰ੍ਹਾਂ ਦੀ ਤਰੇਜ਼ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਨਾ ਲਿਆਂਦਾ ਜਾਵੇ ਅਤੇ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕਰਵਾ ਕੇ ਜਗ੍ਹਾ ਦੀ ਤੁਰੰਤ ਮੁਰੰਮਤ ਕਰਵਾਈ ਜਾਵੇ।
4. ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਫਟੀ ਦੀ ਜਿੰਮੇਵਾਰੀ ਸੰਸਥਾ ਦੀ ਹੋਵੇਗੀ। ਅੱਗ ਬੁਝਾਊ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਹੋਣੇ ਚਾਹੀਦੇ ਹਨ।
5. ਜੇਕਰ ਕਿਸੇ ਕੁਦਰਤੀ ਆਫ਼ਤ ਕਾਰਨ ਜਾਂ ਕਿਸੇ ਵੀ ਕਾਰਨ ਬਿਲਡਿੰਗ ਦਾ ਨੁਕਸਾਨ ਹੁੰਦਾ ਹੈ ਤਾਂ ਤੁਰੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ।
6. ਜੇਕਰ ਬਿਲਡਿੰਗ ਵਿੱਚ ਕਿਸੇ ਤਰ੍ਹਾਂ ਦਾ ਵਾਧਾ ਕਰਨਾ ਹੋਵੇ ਤਾਂ ਆਰਕੀਟੈਕਟ ਤੋਂ ਪਾਸ ਕਰਵਾਇਆ ਜਾਵੇ ਅਤੇ ਇਸ ਸਬੰਧੀ ਇਸ ਦਫਤਰ ਨੂੰ ਵੀ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ।
7. ਜੇਕਰ ਭਵਿੱਖ ਵਿੱਚ ਪੰਜਾਬ ਸਰਕਾਰ ਵੱਲੋਂ ਕੋਈ ਵੀ ਰੋਡ ਅਸੈਸ ਜਾਂ ਕੋਈ ਹੋਰ ਫੀਸ ਪ੍ਰਾਪਤ ਕਰਨ ਲਈ ਹਦਾਇਤਾਂ ਪ੍ਰਾਪਤ ਹੁੰਦੀਆਂ ਹਨ ਤਾਂ ਉਹ ਫੀਸ ਆਪ ਦਾ ਸਕੂਲ ਭਰਨ ਲਈ ਪਾਬੰਦ ਹੋਵੇਗਾ। ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਆਪ ਨੂੰ ਬਿਨਾਂ ਕੋਈ ਨੋਟਿਸ ਦਿੱਤੇ ਜਾਰੀ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਕੀਤਾ ਜਾ ਸਕਦਾ ਹੈ।

ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,  
ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ: 226  
ਮਿਤੀ: 28-08-2023 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,  
ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।



# PERFORMA FOR THE SAFETY OF THE SCHOOL BUILDING

(To be filled by the Head of the School)

(Part-I)

1. Name of the school : Sh. Swinder Kumar Gupta Sarvhitkari Vidya Mandir
2. Location : Buna Gujar Road, Sarvhitkari School Wali Gali
3. Plot Area : 31K, 6M
4. Plinth Area : G.F - 15384.65 sq. ft 1st floor 12149.90 sq. ft
5. Number of Stories: Two
6. Year of the construction of the building 2003, 2011, 2013
7. If the building has been construction under supervision of qualified engineering of the following detail may be given:-
  - (a) Name of the engineer with qualification  
Swinder Architect (Chartered engineer values)
  - (b) Address of the Engineer  
Sei Muktsar Sahib
  - (c) Set of structure drawing used in the construction, if available  
.....
  - (d) Name & Address of the Architect Charanjeet Kaur Bhatia D. Architect  
LIC No. 000796 M.C.M
8. Whether the building has been constructed for the purpose of:
 

(a) School	Yes/No
(b) Residential purpose & converted for as a school.	Yes/No
9. Material used for roofs:
 

(a) R.C.C Slabs	Yes/No
(b) R.S. Joists & batons	Yes/No
10. Material used
 

(a) Mud Mortar	Yes/No
(b) Cement Mortar	Yes/No
(c) Plaster	(i) Line Mortar Yes/No
	(ii) Cement Mortar Yes/No
11. Flooring:
 

(a) Conglomerate	Yes/No
(b) Terrazzo	Yes/No
(c) Brick Paving	Yes/No
12. A detail drawing indicating dimensions of the rooms along with size.

  
 (Stamp & Signature of School)  
 Sarvhitkari Vidya Mandir (Sen. Sec)  
 Sei Muktsar Sahib (Regd. No: 1630413)



(Part-II)

I have visited the above mentioned school on 28/8/23 and have visually Inspected it from all angles of safety and I find it for the normal use as school building.


(a) In case any addition/Alternation or expansion and modification to this building is to be carried out, the same be carried out under the supervision of a technically Qualified engineer and this certificate may again be obtained after the completion From the under signed.

(b) In case the building is affected by flood or if there is settlement of walls, foundation, Sagging of roofs etc. Immediate inspection of the stability and safety of the building Must be carried out again.


(c) This building can be safety occupied for normal use upto 31/3/2024

Buldy seems to be Safe in  
normal condition  
✓

(Mention the date upto which it can be safety used.)

  
Sub Divisional Engineer,  
Provl. Sub Divn. PWD B&R Br.  
Sri Muktsar Sahib

C/S

  
Executive Engineer,  
Construction Div. PWD  
Sri Muktsar Sahib